J.K. Technologies, Ll.C. 3500 Sweet Air St. Baltimore, MD :21211 (410) 366-8332 (410) 366-7655 (fax) convert2us@aol.com Registered Importer R-90-006

NHTSH-02-11647-1
Petition For Import Eligibility Determination

IAW 49 CFR 593.5 (A) (1) CONFIDENTIAL ADDENDUM ATTACHED

January 23,2002

Administrator
O.V.S.C.
National Highway Traffic Safety Administration
Room 6111
400 7th St., S.W.
Washington, DC. 20590

Attn.: NEF-32 Import Eligibility

Dear Mr. George Entwistle,

The following is the basis for this petition:

Part 593.6(a) (1)

The vehicle for which a determination is sought is Audi A4/S4 2001. We have examined the recall campaigns and we have found that there were no listings for these vehicles. All vehicle reports will have a recall campaign search included with them at the time of submission.

Part 593.6(a) (2)

The vehicle which is substantially similar to the petition vehicle is the US version.

Part 593.6(a) (3)

The vehicle which we believe to be substantially similar is manufactured for sale in the USA and it was certified to meet all applicable Federal Motor Vehicle Safety Standards ("FMVSS") in effect at the time of manufacture. The non-

J.K. Technologies, L.L.C.

Page 1

January 23,2002

conforming model was not listed on the accepted DOT list in 55 FR 219, pp219, 47418ff, α the updates that have been published. The differences between the USA model and the non-certified model are very mirror and have been outlined in this petition,

Part 593.6(a) (4)

Since a USA companion model exists, we seek your determination that our petition vehicle is substantially similar to the USA model and therefore is eligible for importationand modification in the "substantially similar" category. We have examined the printed text from the dealers both in the USA and in Europe and we have compared the parts lists from Europe and the USA to determine both what differences exist and what parts will be necessary to bring our non-conforming model into conformance with air applicable FMVSS in effect at the time of manufacture. These differences and changes have been outlined in the following examination of each applicable FMVSS-

Part 593:6(a) (5)

The following outline will show that our non-conforming vehicle was originally manufactured to conform to the FMVSS in many areas in the same manner as its U.S. companion model, many of the concerned parts have the same parts numbers as the USA model. In all areas that have to be modified the parts will be supplied by the OEM manufacturer. The modifications to this vehicle do not concern the basic structure; only easily removable and available parts.

FMVSS 101

These systems are included in the instrument cluster. The replacement cluster are available from the dealer and the reprogramming will allow the C.A.N. system to accept the changes.

FMVSS 102

The markings, starter interlock, shifting pattern, and brake effect are identical to those in the U.S. model.

FMVSS 103

The windshield defogging and defrusting systems are identical to those in the U.S. model.

The windshield wiping and washing systems are identical to those in the US.

FMVSS 105 - FMVSS 135

The hydraulic brake system and the parking brake system are identical to those in the U.S. model.

FMVSS 106

The brake hoses are identical to those in the U.S. model.

FMVSS 108

The following modifications must be made to fully meet this FMVSS:

- a. Install U.S. modal headlamps and front sidemarker lights
- b. Install U.S. model taillamp assemblies which incorporate rear sidemarker lights.
- c. Inspect the U.S. model high-mounted stop light assembly.

FMVSS 109

This vehicle came equipped with tires that bare the "DOT" symbol.

FMVSS 110

A tire placard must be installed to meet this FMVSS requirement.

ENW/66 114

The driver's inside and outside rearview mirrors meet this FMVSS. However, the passenger's rearview outside mirror must be changed to the US. companion model part to meat the requirements. See Attachment (Mirror part#) or be etched to read the appropriate language.

FMVSS 113

The hood latch system is identical to the one used on the U.S. model.

J.K. Technologies, L.L.C.

Page 3

January 23, 2002

The key warning system are programmed at the time that the instrument cluster is changed. These systems must be inspected at the time of conversion.

CFR 541

This vehicle may require "anti-theft Markings" to comply with this standard. Cars imported must be inspected and labled as needed.

CFR 565

A "Vehicle Identification Plate" must be added near the left windshield post and a reference and certification label must be added in the left front door post area to meet this FMVSS- Copies of all labels will be included in the final report.

FMVSS 116

The vehicle came equipped with DOT brake fluid and the top of the master cylinder is labeled with the DOT information.

FMVSS 118

The windows do not operate with the key off. These systems are the same as the USA models.

FMVSS 124

The accelerator control system is identical to the U.S. model.

FMVSS 201

The components subject to this FMVSS are identical to those in the U.S. companion model.

FMVSS 202

This vehicle came equipped with head restraints that are identical to those on the U.S. model,

N/A when FMVSS 208 is met. Conforms to S5.1 of FMVSS 208.Impact for steering controls systems.

FMVSS 204

The steering shaft on this vehicle are energy absorbing and is identical to that used on the U.S. model.

FMVSS 205

The glass and glazing materials used on this vehicle are identical to those used on the U.S. model. They are clearly labeled with DOTAS-I or DOTAS-2,

FMVSS 206

The door, locks and retention components are identical to the USA model.

FMVSS 207

The seating system in this vehicle is identical to that used in the U.S. model.

I MVSS 208

This vehicle is equipped with a seat belt warning lamp and audible warning that is identical to that used on the U.S. model. The passive restraint systems used in these vehicles consist of dual front airbags and knee bolsters, They also have combination lap and shoulder belts at the out board front seating positions as well as at the rear outboard seating positions. These manual systems are automatic, self-tensioning and are released by means of a single red push-button.

All vehicles entering the U.S.A. must be inspected to confirm that the systems bare the U.S. part # or the airbags (Part# - See Attachment), control unit (part#
Me Attachment), sensors and seatbelts and that the knee bolster (part#-See Attachment) has been installed. Some parts coming from European countries may need to be changed due to varying regulations, However, Gulf states vehicles have U.S. systems as standard equipment.

FMV\$\$ 209

The seatbelt labels are identical to those on the U.S. model and they meet this FMVSS requirement.

FMVSS 210

The seatbelt anchorages are identical to those of the U.S. model.

The windshield intrusion zone and the parts and engineering thereof are identical to those of the U.S. model.

FMVSS 214

Doorbars in this vehicle are identical to those in the USA model.

49 CFR 581 or FMVSS 215

The bumpers and the support structure for the bumpers on these vehicles are identical to the U.S. model.

FMVSS 216

The body of these vehicle is identical to that of the U.S. model.

FMVSS 219

The windshield intrusion and the parts α components thereof, are identical to those of the U.S. model.

FMVSS 301

The fuel system in this vehicle are identical to that of the U.S. model. Fuel spillage problems are controlled by the evaporative system that was installed by the factory for the

A requirements. These evaporative systems have a rollover and check valve incorporated in their design.

FMVSS 302

This vehicle is equipped with interior materials that are identical to those used on the U.S. model.

Thank you for your attention,

J.K. Technologies, L.L.C.

By: Jonathan Weisheit, President

加 小川 25 . 戸 多 30